



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2591

Work Order Type: Weatherization

Audit Name: 14014SO2591

CLIENT INFORMATION

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Address: , Unit 1276

FAYETTEVILLE, TN 37334

AGENCY INFORMATION

Agency: South Central Human Resource Agency

Address: (PO Box 638) 1437 Winchester Highway
Fayetteville, TN 37334

Agency Phone: (931) 433-7182

Fax: (931) 433-0074

Email Address:

Agency Contact: WILLIAMS, ROBERT

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 1 of 10

Measures

Measure 1 Infiltration Redctn

Components

Inspected

Comment AFTER INSTALLING NEW DOORS AND WINDOWS, USE BLOWER DOOR TO FIND AIR INFILTRATION. SEAL ANY DOOR AND WINDOW FRAME, CROWN MOLDING, ELETRICAL AND PLUMBING INTRUSION THAT HAS AIR INFILTRATION.REPAIR HOLE UNDER BATH SINK, CAULK AROUND BATH TUB.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Miscellaneous Su	Infiltration Reduction	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 User-Spec Ceiling R

Components 1

Inspected

Comment INSTALL ACCESS, 1X12 PLYWOOD BOX,6" INSULATION ON LID, 2 LATCHES, 4 RULERS, BAFFLES, FLAG WHERE NEEDED. POST INFO SHEET NEAR ACCESS, AND SEND COPY TO OFFICE WITH FINAL BILL.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - R-38	SqFt	1080	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	0	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 2 of 10

Measure 3 POP OFF PIPING

Components

Inspected

Comment INSULATE FIRST 6' OF HOT & COLD. INSTALL POPOFF PIPING.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3			Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
		As per SWFG standards 2.4.1 (page 2-11).							

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Measure 4 Replace Htg. System

Components 1

Inspected

Comment INSTALL HI-EFFICIENCY(81%) DIRECT VENT NG HEATER WITH FAN.
SIZED TO HEAT 1000 SQ FT . RUN NEW WIRE TO FAN FROM BREAKER
BOX.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Heating Equipme	Space Heater - 39 kBtu/h NG Existing, 23 - 32 kBtu/h NG Post	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 3 of 10

Measure 5 Refrigerator Rplcmnt**Components****Inspected**

Comment INSTALL NEW REFRIGERATOR NO LARGER THAN 21 CU FT, PLAIN WHITE, ENERGY STAR RATED.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
10	Refrigerators	REFRIGERATOR-	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
11	Labor	Installation Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 4 of 10

Measure 6 Lighting Retrofits**Components** KIT,LV**Inspected****Comment** INSTALL 3 SMALL BASED BULBS.13'S
INSTALL 2 IN KITCHEN.25'S☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl. - 25 Watt	Each Lamp	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Compact Fl. - 25 Watt	Each Lamp	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Miscellaneous Su	Added Misc Cost	Each	2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
4	Lighting	Compact Fl. - 13 Watt	Each Lamp	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
5	Labor	Compact Fl. - 13 Watt	Each Lamp	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
6	Miscellaneous Su	Added Misc Cost	Each	3	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 5 of 10

Measure 7 Floor Ins. R-19**Components** 1**Inspected****Comment** INSTALL R-19 FLOOR INSULATION AND ACCESS COVER, 2 PART FOAM PERIMETER SILL.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1080	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:****Measure 8 Wall Insulation****Components** E,N,S,W**Inspected****Comment** DENSE PACK WALL ON FRONT
DENSE PACK WALL.SOUTH SIDE
DENSE PACK WALL.EAST SIDE
DENSE PACK WALL.NORTH SIDE☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	908.2	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	LABOR	Each	0	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 6 of 10

Measure 9 Low-E Windows**Components** N4,E2,E,S3,S2**Inspected**

Comment REGLAZE FRT 46X56
REGLAZE & SEAL A/C'S (2)
REPLACE 28X37 S SIDE
REPLACE 46X54 S SIDE
REPLACE 36X38 EAST SIDE
REPLACE 46X54 EAST SIDE
REPLACE 46X54 N SIDE

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Windows	Low E Window	SqFt	68.44	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Low E Window	SqFt	68.44	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
3	Other	Low E Window	Each Window	5	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
4	Miscellaneous Su	Total Added Misc Cost	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Measure Sub Total:**Sub Total:****Field Notes:**

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 7 of 10

Measure 10 Fix Improper Venting (Clothes Dryer)**Components****Inspected****Comment**☐

INSTALL METAL FLEX AND VENT TO OUTSIDE.

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Cap / 4" rigid / connections Vent to exterior and cap. Approx 7ft.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:**Measure 11 Practice Lead Safe Weatherization (Walls)****Components****Inspected****Comment**☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Equipment	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 8 of 10

Measure 12 Smoke Detector is Needed**Components****Inspected****Comment**

INSTALL SMOKE/CO MONITER.

☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector / CO detector Combo Install detectors	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:**Measure 13 Vapor Barrier Needed
(Basement/Crawlspace)****Components****Inspected****Comment** Install vapor barrier on ground and 6" up foundation wall and secure.☐

#	Material / Labor	Description / Comment	Units	Qty	Estimated		Actual		
					Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	6 mil poly Install vapor barrier on ground and 6" up foundation wall and secure.	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:	<input type="text"/>	

Field Notes:**Work Order Grand Total:****Grand Total:**

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 9 of 10

Client Name:

Client ID: 14014SO2591

Alt. Client ID: LINCOLN

Work Order (Bid Form)

Work Order Name: 14014SO2591

Report Run On: 10/6/2011

DOE Weatherization Assistant

Version 8.6.0

Page 10 of 10